

Less than a case of dynamite, a box of electric detanators and

assorted steel tools carried together in the box of a dump truck

resulted in an explosion which killed the driver and severely

injured a nearby child.

Explosives Transportation Permit must be

- any conditions. 4. No other materials may be carried with

The Queen's Printer Ottawa, Canada 1969

EXPLOSIVES DIVISION

OTTAWA, CANADA

J. J. GREENE MINISTER C. M. ISBISTER

Cat. No.: M82-569

DEPARTMENT OF ENERGY, MINES AND RESOURCES.

CAI

MS

-Z 110


3 1761 11550280 9

1. The vehicle must not be overloaded - 80%

VEHICLE

carrying box.

- 1. The vehicle must be suitable for carrying explosives.
- There must be no lights or heating system in the
- 2. A towed vehicle must not be used for explosives. However, a truck tractor with semi-trailer is excepted.
- 3. The carrying box must be strong enough and high enough
- to ensure that the explosives will not fall out.
- 4. Exposed iron or steel in the carrying box must be covered with wood or other non-sparking material.





- DRIVER
 - - 1. In open vehicles the explosives shall be covered with a fire-resistant tarpaulin.
 - 2. A fire extinguisher large enough to deal with a apsoline
 - or oil fire must be carried.

FIRE PRECAUTIONS

- 3. Smoking is not allowed in or near the vehicle. 4. No matches may be carried (except safety matches in the cab if essential).



INSPECTION

LOADING AND UNLOADING I. Explosives must not be moved unless proper storage is

- ready at destination.
- The vehicle must be serviced with fuel, all and air before
- loading explosives. The ignition must be OFF and the brakes ON during load-

sion of the Regulations.

ing and unloading. Operators of factories and magazines must not allow loading of a vehicle which obviously violates any provi-



- 1. The rules of the road must be strictly observed.
- from all four sides of the vehicle. They must not be

WHILE UNDER WAY





